TN Buchanan Sw.D.

Green Bay

February 18, 1971

Division of Environmental Protection

TO:

Thomas G. Frangos

STIN:

Glen Bishop

FROM:

James L. Lissack

SUBJECT:

Lehrer Sanitary Landfill Operation, Ottagamie County,

Town of Buchanan

This writer conducted a field investigation on February 18, 1971, of Lehrer Brothers Sanitary Landfill. The following were noted:

- 1. Compacting and covering was being conducted.
- 2. Wood and bark chips were being utilized to create a stable working surface and to sponge up water from thawing snow. This appeared to be working excellently.
- 3. An attendant was on duty.
- 4. A large container was placed at the entrance of the site for dumping of garbage from local town residents. This container, when full, is dumped into the landfill. This container is to curtail small traffic from the site.
- 5. Mr. Lehrer was contacted and indicated no burning is done. No evidence of burning was found.
- 6. The dumping area to the south of the landfill has been discontinued.
 All refuse is now being placed in the sanitary landfill portion.

It is the conclusion of this writer that the sanitary landfill operated by Lehrer Brothers is being conducted in conformance with Chapter RD 51.

Ву	
	Dennis C. Weisensel
	Environmental Technician

DCW:jp

NOTED:

00554

DEPARTMENT OF NATURAL RESOURCES Solid Waste Disposal - Site Evaluation

Licensee <u>Zehrer</u> Brother License No.				
Officials: (Mayor, Chairman, Pres.)				
(Clerk)				
Responsible Person Phone				
Location Oulagen	io B	ucharan		
(county	(towns			
		Population served		
Distances to: surface water		nearest dwelling		
groundwater	bedrock	S.T.H. 15 mul 3		
OPERATION CHECK LIST	YES NO	REMARKS		
Screened from view	(15()			
Lockable gate at entrance	(1) (1)			
Regulatory signs posted	() (1) ei	there by fernit only		
All-weather approach road	(S()			
Nuisance free (odors, loose paper, etc.)	(50)	Last several pieces of		
Site fenced	()()	equipment in fire -		
Operator on duty	(U) ()			
Compaction and covering	(4) (1)	ald parlin class to		
Equipment available	(1)()	public and not being		
Putrescible material covered	(1)	used.		
Rodent and insect control	()()			
Burning practiced	()()			
Fire hazard in area	()(5)			
Hazardous material at site	()(/)			
Site subject to flooding		00553		
Local official contacted	(1)()			
Permit required (60.72 Stats.) (() ()				
Comments				
Data migitad 1 . 18	11	Evaluation by All		